


व्यावसायिक परीक्षण रिपोर्ट  
COMMERCIAL TEST REPORT

संख्या / No. : Imp.119/166  
माह / Month: November, 2012



**MB-5 ROTAVATOR (TRACTOR MOUNTED)**



भारत सरकार  
GOVT OF INDIA

कृषि मन्त्रालय

MINISTRY OF AGRICULTURE

कृषि एवं सहकारिता विभाग

DEPARTMENT OF AGRICULTURE AND COOPERATION

उत्तर पूर्वी क्षेत्र कृषि यंत्र प्रशिक्षण एवं परीक्षण संस्थान

NORTH EASTERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE

विश्वनाथ चारिआलि, जिला-शोणितपुर (असम)

BISWANATH CHARIALI :: SONITPUR :: ASSAM, PIN - 784 176

Website: <http://nerfmtti.dacnet.nic.in>

Ph. No. 03715-222094

Fax No: 03715-230358

E-Mail: [fmti-ner@nic.in](mailto:fmti-ner@nic.in)

RESEARCH LIBRARY  
NO. 1506 7th FLOOR,  
DATE 2/11/12

Imp.119/166	MB-5 Rotavator (Tractor - Mounted) [ Commercial Test ]	6
-------------	-----------------------------------------------------------	---

#### 4. SPECIFICATIONS

##### 4.1 General:

Manufacturer	: M/s M.B. Farm Machinery (P) Ltd. Ludhiana – Maler Kotla Road, Village Bool, Ludhiana
Name of machine	: Rotavator
Type	: Tractor-Mounted (Gear Drive)
Make	: M.B.
Model	: MB-5
Serial number	: N.A.
Year of manufacture	: N.A.
Type of blade	: Hatchet (L-Shaped)
Working width of implement (mm)	: 1445
Recommended power source	: Not recommended
Prime Mover used during test	: New Holland 5500 Tractor

Imp.119/166	MB-5 Rotavator (Tractor - Mounted) [ Commercial Test ]	23
-------------	-----------------------------------------------------------	----

### 8. EFFECTIVENESS OF SEALINGS

After completion of dry & wet land operation for 25.9 and 15.5 hours respectively, the implement was dismantled for checking the effectiveness of sealing provided against ingress of dust, and water/mud in various sub-assemblies/components. The observations are given in ensuing table:

Sl. No.	Location	Whether ingress of mud and/or water was observed (Yes/No)
1	Primary reduction gear box	No
2	Secondary reduction gear box	No
3	Rotor assembly (hub)	No

### 9. EASE OF OPERATION & ADJUSTMENTS

No noticeable difficulty was observed during the operation and adjustment of rotavator.

### 10. DEFECTS, BREAKDOWNS AND REPAIRS

No noticeable defect or breakdown was observed during 41.4 hours of field operation.



### 11. COMMENTS AND RECOMMENDATIONS

- 11.1 The specifications of implement hitch, in full, do not conform to the IS: 4468 (Part-1)-1997. Hence, it is recommended that implement should be provided with the hitch conforming to relevant Indian standards.
- 11.2 Dimensions of PIC of implement & PIC yoke bore of PTO drive shaft, in full, do not conform to IS: 4931-1995 and, therefore, should be looked into.
- 11.3 Suitable stickers, labeling plates indicating the grade & change period of oil used in gear boxes should be pasted on Rotavator.

Imp.119/166	MB-5 Rotavator (Tractor - Mounted) [ Commercial Test ]	24
-------------	-----------------------------------------------------------	----

- 11.4 Hardness and chemical composition of rotor blades do not conform to relevant Indian Standards. This needs to be looked into for corrective action.
- 11.5 Month/Year of manufacture's name and trade mark, (if any), size of implement and power required should also be indicated on the labeling plate.
- 11.6 **Technical literature:**  
A booklet, named Instructional manual and Parts list was provided for reference during testing.  
The tractor(s), with which machine is considered suitable for operating in the field, should be prominently mentioned in the Technical literature.

**TESTING AUTHORITY**

SANJAY KUMAR AGRICULTURAL ENGINEER	
M. K. VISHWAKARMA DIRECTOR	

Test conducted/report compiled by : P.C. DIHINGIA, STA

**12. APPLICANT'S COMMENTS**

No comments have been received from the applicant on this machine.

Imp.119/166
Place of Tractor
Sl. No.
1
2
4
5
6
7
8
9
10
11
12
13
14
15
16
17