

# व्यावसायिक परीक्षण रिपोर्ट COMMERCIAL TEST REPORT



संख्या / No.: Imp. 213/285

माह / Month: July, 2017



# LANDFORCE, TWO BOTTOM FIXED MOULD BOARD PLOUGH Model :M-2FA (Tractor Mounted)



PATE 29/1/28

भारत सरकार

GOVT OF INDIA

कृषि एवं किसान कल्याण मन्त्रालय

MINISTRY OF AGRICULTURE& FARMERS WELFARE

कृषि, सहकारिता एवं किसान कल्याण विभाग

DEPARTMENT OF AGRICULTURE, COOPERATION & FARMERS WELFARE

उत्तर पूर्वी क्षेत्र कृषि यंत्र प्रशिक्षण एवं परीक्षण संस्थान

NORTH EASTERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE

विश्वनाथ चारिअली, जिला-विश्वनाथ (असम )

BISWANATH CHARIALI :: BISWANATH :: ASSAM, PIN - 784 176

Website: http://nerfmtti.nic.in

Ph. No. 03715-222094

Fax No: 03715-230358

E-Mail: fmti-ner@nic.in

Imp-213/285

# LANDFORCE, TWO BOTTOM FIXED MOULD BOARD PLOUGH Model :M-2FA (Tractor Mounted) [Commercial Test]



### 8.5.1.2.2 Share bar of rear bottom:

S. No.	Notation	Dimension (mm)		Wear (%)	
		Initial	After 26.2 h	After 26.2 h	Per hour
1.	Total length	710	700	1.41	0.05
2.	Width at pointed portion	7.01	1.03	85.31	3.26

Remarks: The hourly percentage of wear on dimension basis was observed as 0.05 to 3.26 %.

#### 8.5.2 On mass basis:

### 8.5.2.1 Share:

S.No.	Initial mass of share (g)	Mass of share after 26.2 h of	Difference (g)	Wear (%)	
		operation (g)		After 26.2 h	Per hour
1	365 (front)	345	20	5.48	0.21
2	350 (rear)	340	10	2.86	0.11

Remarks: The hourly percentage of wear on mass basis was observed as 0.11 to 0.21 %.

### 8.5.2.2 Share bar:

S.No.	Initial mass of share (g)	Mass of share after 26.2 h of	Difference (g)	Wear (%)	
		operation (g)		After 26.2 h	Per hour
1	525 (front)	518	7	1.33	0.05
2	510 (rear)	500	10	1.96	0.07

Remarks: The hourly percentage of wear on mass basis was observed as 0.05 to 0.07 %.

### 9. EASE OF OPERATION AND ADJUSTMENTS

No noticeable difficulty was observed during the operation and adjustment of Two Bottom Fixed M.B plough.

## 10. DEFECTS, BREAKDOWNS AND REPAIRS

No breakdown was occurred during 26.2 h of field test of the Two Bottom Fixed M.B plough.

# 11. SUMMARY OF OBSERVATIONS, COMMENTS AND RECOMMENDATIONS

- 11.1 The dimensions of the share and share bar of plough does not conforms to IS: 10691-1983.
  This should be looked into for corrective action for standardisation.
- 11.2 The dimension of three point linkage, hitch pyramid does not conform to IS: 4468–1997.
  Therefore, this should be looked into for corrective action.
- 11.3 The hardness of the share and share bar does not conform to IS: 10691-1983. This should be looked into for corrective action for standardization.
- 11.4 The carbon content in share bar was not within its range as per IS:10691-1983. This is recommended to looked into for corrective action of standardisation.

FARM MACHINERY TRAINING & TESTING INSTITUTE (NER), B. CHARIALI, BISWANATH, ASSAM

Scanned with CamScanner



# LANDFORCE, TWO BOTTOM FIXED MOULD BOARD PLOUGH Model :M-2FA (Tractor Mounted) [Commercial Test]

Page 16 of 18

The size of sunk headed bolts fixing the share with frog was not as per IS: 10691-1983. This 11.5 is recommended to looked, for corrective measures.

#### 11.6 Labelling plate:

Product, model, serial number and mfg. Year is indicated on the labelling plate. However, it is recommended to specify size and power requirement of the implement.

#### 11.7 Rate of work:

- a) The area cover was recorded as 0.192 to 0.207 ha/h at the speed of operation from 3.15 to 3.41 km/h.
- b) The time required to cover one hectare area was recorded as 4.84 to 5.21h.

#### 11.8 Quality of work:

- a) The depth of cut was recorded as 18 to 20 cm.
- b) Average working width was observed as 68 to 75 cm.
- c) Field efficiency was observed as 80.4 to 90.2 %.
- 11.9 The hourly wear percentage of share on dimension basis was recorded as 0.17 to 0.33 and share bar was recorded as 0.05 to 3.26.
- 11.10 The hourly wear percentage of share on mass basis was recorded as 0.11 & 0.21 and share bar was recorded as 0.05 & 0.07.

#### 11.11 Technical literature :

Operator manual, service manual, parts manual covered with English was submitted along with the implements. However, it is recommended to bring out the same covered with Hindi and other vernacular languages as per IS: 8132-1999

# **TESTING AUTHORITY**

S. G. PAWAR AGRICULTURAL ENGINEER	Sepan
A.K. UPADHYAY SENOIR AGRICULTURAL ENGINEER	M
K.K. NAGLE DIRECTOR	Deceye
Test conducted & Report compiled by	

Test conducted & Report compiled by -

Sh. Rahul Prajapathi& Sh. VithatoKeyho

# 12. <u>APPLICANT'S COMMENTS</u>

We agree with the report. However in respect of non-conformities, we will make the 12.1 improvements in accordance to the relevant BIS Standards in next production line.

FARM MACHINERY TRAINING & TESTING INSTITUTE (NER), B. CHARIALI, BISWANATH, ASSAM