व्यावसायिक परीक्षण रिपोर्ट COMMERCIAL TEST REPORT

संख्या / No. :

Imp. 97/141

माह / Month : October, 2011



TATA-RT-MG-642L-540 ROTAVATOR



भारत सरकार GOVT OF INDIA

कृषि मन्त्रालय

MINISTRY OF AGRICULTURE

कृषि एवं सहकारिता विभाग DEPARTMENT OF AGRICULTURE AND COOPERATION

उत्तर पूर्वी क्षेत्र कृषि यंत्र प्रशिक्षण एवं परीक्षण संस्थान NORTH EASTERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE

विश्वनाथ चारिआलि, जिला-शोणितपुर (असम) BISWANATH CHARIALI :: SONITPUR:: ASSAM, PIN - 784 176

Website: www.dacnet.nic.in/NERFMTTI

Ph. No. 03715-222094

Fax No: 03715-230358

E-Mail: fmti-ner@nic.in

Ilmp. 97/141

TATA-RT-MG-642L-540 Rotavator (Tractor - mounted) [Commercial Test]

2

4. SPECIFICATIONS

4.1 General:

Manufacturer

: TATA STEEL LTD.

AGRICO DIVISION

ARMOURY GROUND ROAD

BISTUPUR, JAMSHEDPUR - 831 001

Name of machine

Rotavator

Type

Tractor-Mounted (Gear drive)

Make

TATA

Model

TATA-RT-MG-642L-540

Serial number

Not available

Year of manufacture

2010

Type of blade

Hatchet (L-Shaped)

Working width of

1725

implement (mm)

Recommended power

: 40-45 HP

source

Prime Mover Used during : New Holland 5500

test

Imp. 97/141 TATA-RT-MG-642L-540 Rotavator (Tractor - mounted) [Commercial Test]

Sl. No.	Location	Whether ingress of mud and/or water was observed (Yes/No)
1	Primary reduction gear box	
2	Secondary reduction gear box	No No
3	Rotor assembly (hub)	No

9. EASE OF OPERATION & ADJUSTMENTS

No noticeable difficulty was observed during the operation and adjustment of rotavator.

10. <u>DEFECTS, BREAKDOWNS AND REPAIRS</u>

No noticeable defect or breakdown occurred during 42.57 hours of field operation.

11. COMMENTS AND RECOMMENDATIONS

- 11.1 The specifications of implement hitch, in full, do not conform to the IS: 4468 (Part-1)-1997. Hence, it is recommended that implement should be provided with the hitch conforming to relevant Indian standards.
- Dimensions of PIC of implement, in full, do not conform to IS: 4931-1995 and therefore, it should be looked into for corrective action.
- 11.3 Dimensions of PIC Yoke bore of PTO drive shaft, in full, do not conform to the requirements of IS: 4931-1995. It should be looked into for corrective action.
- Hardness of rotor blades does not conform to relevant Indian Standards. This needs to be looked into for corrective action.

TATA-RT-MG-642L-540 Rotavator (Tractor - mounted) [Commercial Test]	20
	TATA-RT-MG-642L-540 Rotavator (Tractor - mounted) [Commercial Test]

- Suitable stickers indicating the grade & change period of oil used in gear 11.5 boxes should be pasted on Rotavator.
- A labeling plate indicating the particulars like Make, Model, Serial No., 11.6 month/year of manufacture, manufacturer's name and trade mark, (if any), size of implement & power requirement needs to be provided on a nonwearing part of the implement.

Technical literature 11.7

The following literatures were provided for reference during testing:

- User manual
- Instruction manual & Spares list.

TESTING AUTHORITY

P. K. PANDEY SENIOR TEST ENGINEER	UZn-Involp
M.K. VISHWAKARMA DIRECTOR	MBEN

Imp. 97/141

TATA-RT-MG-642L-540 Rotavator (Tractor - mounted) [Commercial Test]

21

12. APPLICANT'S COMMENTS

Para No.	Our Reference	Applicant's Comments
12.1	11.1	We will do and provide all implements as per Indian Standards IS: 4468(Pt-I) - 1997.
12.2	11.2	Dimensions of PIC of implement will be changed as per IS: 4931-1995.
12.3	11.3	PIC Yoke bore of PTO shaft will be changed as per IS: 4931-1995.
12.4	11.4	Blade Hardness will be changed as per Indian Standards.
12.5	11.5	The Stickers will be put indicating the grade and change period of oil.
12.6	11.6	We will place labeling plate on the Rotary Tiller to include these information's.
12.7	11.7	Leaflet, operator's manual and spare parts, catalogue will be provided.