व्यावसायिक परीक्षण रिपोर्ट COMMERCIAL TEST REPORT

संख्या/No. : Imp.77/117 माह /Month: December, 2010



New Swan Rotavator Model: 6 feet (Tractor Operated)



भारत सरकार GOVT OF INDIA

कृषि मन्त्रालय MINISTRY OF AGRICULTURE

कृषि एवं सहकारिता विभाग DEPARTMENT OF AGRICULTURE AND COOPERATION

उत्तर पूर्वी क्षेत्र कृषि यंत्र प्रशिक्षण एवं परीक्षण संस्थान NORTH EASTERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE


विश्वनाथ चारिआलि, जिला-शोणितपुर (असम) BISWANATH CHARIALI :: SONITPUR:: ASSAM, PIN - 784 176

Website: www.dacnet.nic.in/NERFMTTI

Ph. No. 03715-222094

Fax No: 03715-222374

E-mail: fmti-ner@nic.in



1 SCOPE OF TEST

The scope of test was to check and assess the following: -

LABORATORY TEST:

- Checking of specifications
- Hardness of soil engaging parts (Rotavator blades)
- Chemical analysis of critical components (Rotavator blades)
- Wear analysis of critical components

FIELD TEST:

- Rate of work.
- Quality of work
- Ease of operation, maintenance and adjustments
- Labour requirement
- Defects, Breakdowns & Repairs

2 METHOD OF SELECTION

The implement was directly submitted for test by the applicant at this Institute.

3 TEST PROCEDURES

- IS: 6690-2002: Specification for blades for rotavator for power tillers.
- IS: 4931-2004 Agricultural tractors-Rear Mounted PTO.
- iii) IS: 4468 1997 (Pt-I) Agricultural wheeled Tractors- Rear Mounted three point linkage.
- iv) IS: 11531-2001 Test code for puddler.

SPECIFICATIONS

4.1 General:

Manufacturer

M/s New Swan Enterprises

(Agro Tech Division),

C-213, Phase VIII Focal Point, Ludhiana (Punjab) 141 010

Name of machine

Rotavator (Tractor Operated)

Type

Gear type

Make

New Swan (apa)

Model

6 feet

Serial number

NSE 007

Year of manufacture

2010 (apa)

Type of blade

Hatchet (L - type)

Working width of implement (mm)

1728

10. DEFECTS, BREAKDOWNS AND REPAIRS

The LHS trailing board hinge of the rotavator was broken after completion of 49.22 hours of field operation. Other than that no major defects or breakdowns were observed during 50.76 hours of field operation.

11. COMMENTS AND RECOMMENDATIONS

- The specifications of implement hitch does not conforms to the IS: 4468 (Pt-I)-1997. Hence, it is recommended implement should be provided with the hitch conforming to
- The dimensions of splined end pinion shaft and propeller shaft insert dimensions does not 11.2 conform to IS: 4931-2004. This should be looked into for corrective action.
- The grade and change period of oil used in gear boxes of rotavator should be given in the printed literature and suitable sticker should also be pasted on rotavator.
- It is recommended that arrangement for changing rotor speed to suit wider range of soil
- The labeling plate needs to be provided with implement, to indicate the particulars like 11.5 make, model, year of manufacture, size and recommended power.
- Adequacy of literature: Only one leaflet was supplied with the implement during the 11.7 course of testing .It is therefore recommended that operator's manual, service manual and spare parts catalogue should be provided in English, Hindi and other regional

The cover shall be of reasonable durability and shall be of an appropriate size to protect the internal pages and the binding shall be appropriate and durable for the intended

TESTING AUTHORITY

Hada
43n-Anosh
DEZZW.

NORTH EASTERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE, PO: BISWANATH CHARIALI, DISTRICT: SONITPUR (ASSAM) -784 176

Imp. 77/117

NEW SWAN ROTAVATOR Model: 6 ft (Tractor Operated) - | Initial Commercial Test |

15

12. APPLICANT'S COMMENTS

Para No.	Our Reference	Applicant's comments
12.1	11.1 to 11.8	We have gone through very minutely the comments and recommendations advised by the Institute. In this context way inform you that we will implement the entire recommendations point to point wise.