
LIBRARY COPT

व्यावसायिक परीक्षण रिपोर्ट COMMERCIAL TEST REPORT संख्या / No. :

Imp. 111/158

माह / Month :

May, 2012



GREENSYSTEM RT1016 ROTAVATOR



THE WELL IN

भारत सरकार GOVT OF INDIA

कृषि मन्त्रालय MINISTRY OF AGRICULTURE

कृषि एवं सहकारिता विभाग DEPARTMENT OF AGRICULTURE AND COOPERATION

उत्तर पूर्वी क्षेत्र कृषि यंत्र प्रशिक्षण एवं परीक्षण संस्थान NORTH EASTERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE

> विश्वनाथ चारिआलि, जिला-शोणितपुर (असम) BISWANATH CHARIALI :: SONITPUR:: ASSAM, PIN - 784 176

> > Website: www.dacnet.nic.in/NERFMTTI

Ph. No. 03715-222094

Fax No: 03715-230358

E-Mail: fmti-ner@nic.in

Imp. 111/158

GREENSYSTEM RT1016 Rotavator (Tractor - mounted) [Commercial Test]

6

4. SPECIFICATIONS

4.1 General:

Manufacturer

: M/s Dasmesh Mechanical Works

Amargarh, Dist: Sangrur

Punjab - 148 022

Name of machine

Rotavator

Type

Tractor-Mounted (Gear drive)

Make

GREENSYSTEM

Model

: RT1016

Serial number

1PYRT101HB6000013

Year of manufacture

2011

Type of blade

: Hatchet (L-Shaped)

Working width of

1700

implement (mm)

Recommended power

45-55 HP

source

Prime Mover Used during

New Holland 5500, New Holland 7500

test

(4WD)

Imp. 111/158

GREENSYSTEM RT1016 Rotavator (Tractor - mounted) [Commercial Test]

23

8. EFFECTIVENESS OF SEALINGS

After completion of dry & wet land operation for 26.7 and 15.2 hours respectively, the implement was dismantled for checking the effectiveness of sealing provided against ingress of dust, and water/mud in various sub-assemblies/components. The observations are given in ensuing table:

Sl. No.	Location	Whether ingress of mud and/or water was observed (Yes/No)
1	Primary reduction gear box	No
2	Secondary reduction gear box	No
3	Rotor assembly (hub)	No

9. EASE OF OPERATION & ADJUSTMENTS

No noticeable difficulty was observed during the operation and adjustment of rotavator.

10. DEFECTS, BREAKDOWNS AND REPAIRS

No noticeable defect or breakdown was observed during 41.9 hours of field operation.

11. COMMENTS AND RECOMMENDATIONS

- The specifications of implement hitch, in full, do not conform to the IS: 4468 (Part-1)-1997. Hence, it is recommended that implement should be provided with the hitch conforming to relevant Indian standards.
- Dimensions of PIC of implement, in full, do not conform to IS: 4931-1995 and therefore, it should be looked into for corrective action.
- 11.3 Chemical composition of rotor blades does not conform to relevant Indian Standards. This should be looked into for appropriate action.

Imp. 111/158

GREENSYSTEM RT1016 Rotavator (Tractor - mounted) [Commercial Test]

24

- Suitable stickers/labeling plate indicating the grade & change period of oil used in gear boxes should be provided on Rotavator.
- 11.5 Month/year of manufacture, manufacturer's name and trade mark, (if any), size of implement and power requirement should also be indicated on the labeling plate.
- 11.6 **Technical literature**

The following literatures were provided for reference during testing:

- Operator and service manual
- Parts catalogue

TESTING AUTHORITY

M. K. VISHWAKARMA DIRECTOR

MB EM

Test conducted/report compiled by:

P. LODH SENIOR TECHNICAL ASSISTANT Parky wh

o. 111/158

GREENSYSTEM RT1016 Rotavator (Tractor - mounted) [Commercial Test]

25

12. <u>APPLICANT'S COMMENTS</u>

ra D.	Our Reference	Applicant's Comments
.1	* 11.1 ·	We agree and will provide implement hitch conforming to Indian Standards IS: 4468-1997 (Part-1).
.2	11.2	We will make necessary corrections to dimensions of PIC to conform to IS: 4931-1995
.3	11.3	The blades are manufactured using Boron Steel (27MnCrB5-2) conforming to EN10083 – 3. On the basis of wear analysis test, the wear limit was found within acceptable limits and hence, we would prefer to maintain chemical composition as actually observed during chemical analysis.
.4	11.4	Suitable stickers on gearboxes indicating the grade and oil change period will be provided.
.5	11.5	These parameters will be indicated as per the recommendation.