व्यावसायिक परीक्षण रिपोर्ट COMMERCIAL TEST REPORT



संख्या / No. : Imp. No. 156/207


माह / Month: July, 2014



New Swan (NSERT 125) Rotavator

Lis. copy





भारत सरकार GOVT OF INDIA कृषि मन्त्रालय

MINISTRY OF AGRICULTURE कृषि एवं सहकारिता विभाग

DEPARTMENT OF AGRICULTURE AND COOPERATION

उत्तर पूर्वी क्षेत्र कृषि यंत्र प्रशिक्षण एवं परीक्षण संस्थान NORTH EASTERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE

विश्वनाथ चारिआलि, जिला-शोणितपुर (असम)

BISWANATH CHARIALI :: SONITPUR :: ASSAM, PIN - 784 176

Website: http://nerfmtti.dacnet.nic.in

Ph. No. 03715-222094

Fax No: 03715-230358

E-Mail: fmti-ner@nic.in

1. SCOPE OF TEST

The scope of test was to check and assess the following: -

1.1 LABORATORY TEST:

- Checking of specifications
- Hardness of soil engaging parts (Rotavator blades)
- Chemical analysis of critical components (Rotavator blades)
- Wear analysis of critical components (Rotavator blades)

1.2 FIELD TEST:

- Rate of work
- Quality of work
- Ease of operation, maintenance and adjustments
- Labour requirement
- Defects, Breakdowns & Repairs

2. METHOD OF SELECTION

The implement was directly submitted by the applicant for test at this Institute, hence method of selection does not arise.

3. TEST PROCEDURES

i) IS: 6690-2002 : Specifications of blades for rotavator and power tillers

ii) IS: 4931 – 1995 : Agricultural tractors-Rear Mounted PTO

iii) IS: 4468 – 1997 : Agricultural wheeled Tractors- Rear Mounted three (Part-1) point linkage.

iv) IS: 11531 - 2001: Test code for puddler

4. SPECIFICATIONS

4.1 General:

Manufacturer : New Swan Multitech Limited.

Village Raian, Kohara-Macchiwara

P.O.-Heeran, Ludhiana,

Punjab-141112

Name of machine : Rotavator

Make : NEW SWAN

Model : NSE RT 125 Rotavator

Type : Gear Drive

Serial number : NSE 004150

FARM MACHINERY TRAINING & TESTING INSTITUTE (NER), B. CHARIALI, SONITPUR, ASSAM

Year of manufacture

: 2014

Type of blade

: Hatchet (L-Type)

Working width of implement(mm)

1260

Recommended power source

30 - 35 hp Tractor

Prime mover used during test

: John Deer 5310 collar shift Tractor

4.2 Constructional Details (Refer Fig.1):




Fig.1: NEW SWAN (NSE RT 125) Rotavator

KEYWORDS:

- 1. Mainframe
- 2. Side plate
- 3. Rotor shaft
- 4. Rotor blade

- 5. Primary reduction gear box
- 6. Secondary reduction gear box
- 7. Skid
- 8. Hitch pyramid

8. EFFECTIVENESS OF SEALINGS

After completion of dry & wet land operation for 25.7 and 15.1 hours respectively, the implement was dismantled for checking the effectiveness of sealing provided against ingress of dust, and water mud in various sub-assemblies/components. The observations are given in ensuing table:

SL No.	Location	Whether ingress of mud and/or water was observed (Yes/No)
1.	Primary reduction gear box	No
2.	Secondary reduction gear box	No
3.	Rotor assembly (hub)	No

9. EASE OF OPERATION & ADJUSTMENTS

No noticeable difficulty was observed during the operation and adjustment of rotavator.

10. <u>DEFECTS, BREAKDOWNS AND REPAIRS</u>

No noticeable defect or breakdown was observed during 40.8 hours of field operation.

11. COMMENTS AND RECOMMENDATIONS

- 11.1 The specifications of implement hitch, does not conform to the IS: 4468 (Part-1)-1997. Hence, it is recommended that implement should be provided with the hitch conforming to relevant Indian Standards.
- Dimensions of PIC of implement does not conform to IS: 4931-1995 and therefore, it should be looked into for corrective action.
- 11.3 Chemical composition of rotor blade does not conform to IS: 6690-2002. This needs to be looked into for corrective action in production level.
- 11.4 Size of implement and power requirement should also be indicated on the labeling plate.
- 11.5 Technical literature:

A booklet, named Instruction manual and Parts list was provided for reference during testing. Hence, other literature such as parts catalogue, service manual etc. should also be provided with the implement.

However, it is recommended to bring out the manuals also in Hindi and other vernacular . languages as per IS: 8132-1999.

12. APPLICANTS COMMENTS

No comments have been received from the applicant on this machine.