# व्यावसायिक परीक्षण रिपोर्ट **COMMERCIAL TEST REPORT**

# संख्या / No. : Imp.172/224 HIE / Month: March . 2015



# SHAKTI MAHAAN, SMR - 5 ROTAVATOR (GEAR DRIVE)

2;5. 10P1

1785



भारत सरकार

27/8/15

GOVT OF INDIA कृषि मन्त्रालय

MINISTRY OF AGRICULTURE कृषि एवं सहकारिता विभाग

DEPARTMENT OF AGRICULTURE AND COOPERATION उत्तर पूर्वी क्षेत्र कृषि यंत्र प्रशिक्षण एवं परीक्षण संस्थान **NORTH EASTERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE** विश्वनाथ चारिआलि, जिला-शोणितपुर (असम)

BISWANATH CHARIALI :: SONITPUR :: ASSAM, PIN - 784 176

Website: http://nerfmtti.dacnet.nic.in

Ph. No. 03715-222094

Fax No: 03715-230358

E-Mail: fmti-ner@nic.in

#### 1. <u>SCOPE OF TEST</u>

The scope of test was to check and assess the following:

## **1.1 LABORATORY TEST:**

- Checking of specifications
- Hardness of soil engaging parts
- Chemical analysis of critical components
- Wear analysis of critical components

#### **1.2 FIELD TEST:**

- Rate of work
- Quality of work
- Ease of operation, maintenance and adjustments
- Labour requirement
- Defects, breakdowns & repairs

#### 2. METHOD OF SELECTION

The implement was directly submitted by the applicant for test at this Institute, hence method of selection is not known.

### 3. <u>TEST PROCEDURES</u>

The implement was tested in accordance with the following Indian Standard codes:

- i) IS: 6690-1981 (Reaffirmed in 2002)
- ii) IS: 4931 1995 (Reaffirmed in December 1999)
- iii) IS: 4468 1997 (Part-1) (Reaffirmed in 2012)
- iv) IS: 11531 2001

- : Specifications of blades for rotavator and power tillers
- : Agricultural tractors-Rear Mounted PTO shaft (Types 1, 2 & 3)
- : Agricultural wheeled Tractors- Rear Mounted three point linkage.
- : Test code for puddler

#### 4. <u>SPECIFICATIONS</u>

4.1 General:

Manufacturer

Name of machine

Make

Model

Type

- : M/s. Shakti Mahaan Agro Industries Bye Pass Road, Sirhind -140406 Distt.-Fatehgarh Sahib, Punjab
- : Rotavator
- : Shakti Mahaan Agro Industries
- : Shakti Mahaan SMR- 5
- : Tractor Mounted

| Imp. No. 172/224                | -                   |   | R-5 Rotavator (Gear Drive)<br>mercial Test]   | 5 |  |
|---------------------------------|---------------------|---|---|---|--|
| Size of rota                    | vator (mm)          | : | 1500 x 435                                    |   |  |
| Serial number                   |                     | : | Not Specified                                 |   |  |
| Year of man                     | Year of manufacture |   | Not Specified                                 |   |  |
| Type of blac                    | le                  | : | Hatchet (L-shaped)                            |   |  |
| Working width of implement (mm) |                     | ÷ | 1500  |   |  |
| Recommend                       | led power source    | : | 35 to 40 hp                                   |   |  |
| Prime move                      | er used during test | : | Swaraj 855 FE tractor<br>(Refer Annexure-III) |   |  |

# 4.2 Constructional Details (Refer Fig.1)




Fig.1: Schematic view of Shakti Mahaan, SMR-5 Rotavator

## **KEYWORDS:**

- 1. Mainframe
- 2. Side plate
- 3. Rotor shaft
- 4. Rotor blade

- 5. Primary reduction gear box
- 6. Secondary reduction gear box
- 7. Skid
- 8. Hitch pyramid

Imp. No. 172/224

## Shakti Mahaan, SMR-5 Rotavator (Gear Drive) [Commercial Test]

18

| Sl.<br>No. | Initial mass<br>of blade (g) | Mass of blade<br>after 40.9 hours<br>of operation (g) | Difference (g) | Percentage of<br>wear (%) in<br>40.9hrs | Percentage of<br>wear per hour<br>(%) |
|------------|------------------------------|---|----------------|---|---------------------------------------|
| 1.         | 1038.0                       | 978.5   | 59.5           | 5.73                                    | 0.14                                  |
| 2.         | 1050.5                       | 989.0   | 61.5           | 5.85                                    | 0.14                                  |
| 3.         | 1066.5                       | 988.5   | 78.0           | 7.31                                    | 0.18                                  |
| 4.         | 1044.0                       | 976.0   | 68.0           | 6.51                                    | 0.16                                  |
| 5.         | 1050.0                       | 978.5   | 71.5           | 6.81                                    | 0.17                                  |
| 6.         | 1024.0                       | 993.5   | 30.5           | 2.98                                    | 0.07                                  |

Remarks: - The hourly percentage wear of blades on mass basis were recorded as 0.07 to 0.18 %.

## 7.7 Service and maintenance

Requires checking & tightening of all nuts & bolt of the implements especially blade, lower hitch clamps and propeller shafts bolts. The trash and soil wrapped on the rotor axle need to be removed after the day's operation.

### 7.8 Ease of operation & adjustments

The operator can easily adjust and control the implement from operator's seat in the field as the adjustments are within the easy reach of operator. However the operator has to get down from the tractor in order to raise/ lower the depth adjusting skid.

#### 8. DEFECTS, BREAKDOWNS AND REPAIRS

| Sl. No. | Defects, breakdowns and repairs   |      |
|---------|---|------|
| 1       | No major difficulty was observed during the entire test of the<br>implement. However, the strength of MS bracket provided for<br>lifting the trailing board was not found adequate as it was observed<br>got bend during operation. | 15.8 |

## 9. <u>COMMENTS AND RECOMMENDATIONS</u>

- 9.1 The dimensions of the three point linkage (hitch pyramid) of the rotavator do not conform to Ct. I & Cat. II to IS: 4468-2012. This should be looked into for corrective action for standardization.
- 9.2 Dimensions of PIC and PIC yoke bore of implement, do not conform to IS: 4931-1995 and therefore, it should be looked into for corrective action.
- 9.3 Chemical composition of rotor blades does not conform to IS: 6690-2002. The percentage of carbon, silicon and manganese content in composition of rotavator blade material was recorded as 0.323, 0.285, and 1.148% respectively. The carbon and silicon were on lower side and manganese content on higher side when compared with the relevant Indian Standard. It is therefore, recommended that the material of rotavator blade should be improved and provided as per requirement of Indian Standard.
- 9.4 The rate of work was recorded 0.32 to 0.38 ha/h at forward speed of 2.83 to 3.90 kmph in dry land operation.

# FARM MACHINERY TRAINING & TESTING INSTITUTE (NER), B. CHARIALI, SONITPUR, ASSAM


- 9.5 The depth of operation in dry land field was recorded as 5.0 to 8.0 cm with soil moisture content of 10 to 14% in medium soil and considered on lower side for dry land operation. The depth of puddled was recorder as 27 to 31 cm which is considered as normal for such operation.
- 9.6 The field performance of rotavator was evaluated in medium soil. The hourly rate of wear of blade on mass basis were recorded as 0.07 to 0.18 %. The average wear of blade is considered as on higher side.
- 9.7 The bracket of trailing board got bend after running of 15.8 hours of dry operation which implies that the bracket strength was not adequate. Hence, it should be improved at production level to encounter the stress or to bear the vertical thrust.
- 9.8 Labeling plate is not provided with the implement. Hence, labeling plate along with the specifications such as size of the implement, operating speed, make & model, sl. no., year of manufacture and power requirement are to be provided, during the commercial production of implement.

#### 9.9 **Technical literature:**

Only one page of leaflet is provided with the implement. Hence, it is recommended to provide Owner's manual/Operator's manual and Parts list with the implement to refer by the operator and field personnel.

Also, it is recommended to bring out the manuals in Hindi and other vernacular languages as per IS: 8132-1999.

### TESTING AUTHORITY



Test conducted and report compiled by : P.C. Dihingia, STA and Anshul Pandey, STA(I)

19

FARM MACHINERY TRAINING & TESTING INSTITUTE (NER), B. CHARIALI, SONITPUR, ASSAM

# 10. APPLICANT'S COMMENTS

The copy of draft test report was made available to applicant, but the applicant had not made any comments.

FARM MACHINERY TRAINING & TESTING INSTITUTE (NER), B. CHARIALI, SONITPUR, ASSAM